Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/10001BL0499/1
Work Order Type: Weatherization
Audit Name: 10001BL0499

CLIENT INFORMATION

Client Name: Address:

Client ID: 10001BL0499 , 37804

Alt. Client ID: BLOUNT

AGENCY INFORMATION

Agency: Blount County Community Action Agency

Agency Phone: (865) 983-8411

Address: 3509 Tuckalee Pike **Fax:** (865) 681-1781

Maryville, TN 37803 Email Address:

Agency Contact: Larson, Bruce Work Phone: (865) 310-7333

Cell Phone: (865) 310-7333

Email Address: brujanie@charter.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Auditor: Bruce Larson (865-310-7333)

Audit conducted on 3/31/2012

Site Built: 1968

Client has been remodeling bath. Client needs to install baseboards/light fixture.

Clients HVAC is Gas Pack. Has had gas turned off as unit is not working properly, and causing high utility bills. Could not get Tune up in Repairs on NEAT for HVAC.

Client Name:
Client ID: 10001BL0499
Alt. Client ID: BLOUNT

Work Order (Bid Form)
Work Order Name: WO/10001BL0499/1

Report Run On: 4/9/2012

DOE Weatherization Assistant Version 8.6.0 Page 1 of 6

	filtration Redctn			Componen	ts		ı	Inspected
Comment 1. We	eather Strip DR 3 (32" x80	")						
	am drain lines in Bath	•						
2. FU	ani drain iines in bath							
3. Fo	am around kitchen sink dra	in (appro	x. 2 ")	Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous S		Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Comment HWH	WH Pipe Insulation is "under cabinet" unit. Fromove counter topping. Insula			s (each) Ho	s, client w t/Cold.	ill need		Inspected
Comment HWH	is "under cabinet" unit. From			sulate pipes	s, client w t/Cold.	rill need		Inspected
Comment HWH to rem	is "under cabinet" unit. Fron nove counter topping. Insula	ate 4' wate	er pipes	sulate pipes s (each) Ho <i>Estimat</i> ed	s, client w t/Cold.		Actual	
Comment HWH to rem # Material / Labor	is "under cabinet" unit. From	ate 4' wate	er pipe:	sulate pipes s (each) Ho <i>Estimat</i> ed	s, client w t/Cold.		Actual	
Comment HWH to rem# Material / Labor1 Insulation	is "under cabinet" unit. From nove counter topping. Insula Description / Comment DHW Pipe Insulation	ate 4' wate <i>Units</i> Each	er pipe: Qty 1	sulate pipes s (each) Ho <i>Estimat</i> ed	s, client w t/Cold.		Actual	
Comment HWH to rem# Material / Labor1 Insulation2 Labor	is "under cabinet" unit. From nove counter topping. Insula Description / Comment DHW Pipe Insulation	ate 4' wate <i>Units</i> Each	er pipe: Qty 1	sulate pipes s (each) Ho <i>Estimat</i> ed	s, client w t/Cold.		Actual	
Comment HWH to rem# Material / Labor1 Insulation2 Labor	is "under cabinet" unit. From nove counter topping. Insula Description / Comment DHW Pipe Insulation	ate 4' wate <i>Units</i> Each	er pipe: Qty 1	sulate pipes s (each) Ho <i>Estimat</i> ed	s, client w t/Cold.		Actual	
Comment HWH to rem# Material / Labor1 Insulation2 Labor	is "under cabinet" unit. From nove counter topping. Insula Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	sulate pipes s (each) Ho <i>Estimat</i> ed	s, client w t/Cold.	Qty	Actual	

Report Run On: 4/9/2012

	Measure 3 DWH	I Tank Insulation			Componen	ts		ı	nspected
C	comment 40 Gallo	n Electric							
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
(Other Detail								
				Measur	e Sub Total:] .	Sub Total:	
	Field Notes:								
	There ar	ters (2x6x16) Less that ters (2x6x16) Less that te multiple large sharp	ards pres	ent in a	attic. Will ne dditional cha	added la eed to be arge.)			Inspected
#	Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1		Attic Insulation - Cellulose, Blown - R-38	SqFt	1404		Total			rotar
2	Labor	Attic Insulation - Cellulose, Blown - R-38	SqFt	1404					
3	Miscellaneous Su	Added Misc Cost	Each	1					
(Other Detail								
				Measur	e Sub Total:] .	Sub Total:	
	Field Notes:								

Report Run On: 4/9/2012

Measure 5 Flo	or Ins. R-19			Componen	ts FD 1		I	nspected
Comment HVAC 16" Ce	Trunk splits crawlspace.							
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1404					
2 Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1404					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								
Measure 6 CO	Monitor is Needed			Componen	ts		1.	nspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	CO monitor (+)	Each	1					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	

	Improper Venting of Bat haust Fan	hroom		Componer	its			Inspecte
	I bathroom exhaust 8 feet to lete this prior to installing a			side of hou	ise. Hard	l pipe.		
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Measure 8 Pre	essureRelief Piping Neede	ed		Componer	nts			Inspecte
	s "under cabinet" unit. Fron			4' Pressure	Relief Pi	pe to		Inspecte
Comment HWH i crawls	s "under cabinet" unit. Fron		Add	-	Relief Pi		Actual Unit Cost	Inspecte
Comment HWH i crawls # Material / Labor	s "under cabinet" unit. Fron pace.	nt is open		4' Pressure	Relief Pi	pe to	Actual	
Comment HWH i crawlsp # Material / Labor 0 Unspecified	s "under cabinet" unit. Fron pace. Description / Comment	nt is open <i>Units</i>	Qty	4' Pressure	Relief Pi		Actual	
Comment HWH i crawls # Material / Labor	s "under cabinet" unit. Fron pace. Description / Comment	nt is open <i>Units</i>	Qty	4' Pressure	Relief Pi		Actual	
Comment HWH i crawlsp # Material / Labor 0 Unspecified	s "under cabinet" unit. Fron pace. Description / Comment	nt is open <i>Units</i>	Qty	4' Pressure	Relief Pi		Actual	
Comment HWH i crawlsp # Material / Labor 0 Unspecified	s "under cabinet" unit. Fron pace. Description / Comment	Units Each	Qty 1	4' Pressure	Relief Pi	Qty	Actual	

Report Run On: 4/9/2012

Measure 9 Sm Comment	oke Detector is Needed			Componer	nts		,	Inspected
				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Smoke detector (+)	Each	1					
Other Detail			1			1		
			Measur	e Sub Total:]	Sub Total:	
Moasuro 10 Var	oor Barrier Needed			Componei	nte.			Inspected
(Ba	sement/CrawIspace) has drainage from upper le	ot Koons	crawla	•				·
Comment Chent	ias drainage nom upper i	ot. Reeps	Clawis	Estimate	-	•	Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Basement / crawlspace vapor barrier (+)	Each	1					
Other Detail								
			Measur	e Sub Total:]	Sub Total:	
Field Notes:						1		
		Work O	rder Gra	and Total:		Gran	d Total:	